Supplement to SPB7-230.031.09.01.02 -
Separate Exposure release button, Inst. Instructions - MAMMOMAT 3000

This document contains labels that are to be inserted into the *Manuals for MAMMOMAT 3000.* Following labels are to be cut out and pasted into the Tecnical Manual.

NOTICE!
See SPB7-230.031.09

NOTICE!
See SPB7-230.031.09

Following labels are to be cut out and pasted into the User Manual. The labels are in four different languages, one for the manual in each language.

NOTICE!
When the separate exposure release button has been installed, the two exposure release buttons on the control panel will be out of function, and can not be used.

HINWEIS!
Wenn die separate Belichtungstaste installiert ist, sind die beiden Belichtungstasten auf dem Bedienfeld auβer Funktion und können nicht benutzt werden.

NOTA!
Après l'installation du déclencheur externe, les deux déclencheurs du panneau de contrôle deviennent hors service et ne peuvent plus être utilisés.

NOTA!
Si se ha instalado el botón de disparo de exposición separado, quedarán desactivados y no podrán utilizarse los dos botones de disparo situados en el tablero de control.

Mam0310

Design and Function

ON/OFF button to select/deselect automatic decompression after exposure. When OFF, use the foot switch for motorized decompression or the knobs for manual decompression.

Limit button (acknowledgement). Serves to reset the system after errors, indicated by an error code, or after faulty exposures, indicated also by an acoustic signal and limit lamp being lit (e.g. limit mAs, dose monitoring, interrupted exposure). Flashing limit lamp indicates that the tube temperature is above normal.

Exposure release buttons with green indicator light. Both buttons must be pressed during the entire exposure. This is to ensure that the operator is standing behind the radiation shield during the exposure.

Decompression button (only with the separate control console) to be used in case of emergency. The button must be kept pressed until the breast is decompressed.

Option

Exposure release handle on extension cord is available for the separate control console.

MAM00021

SIEMENS

10

Place label here!

"User Manual"

Mam0311

5-10 PRINCIPLE DIAGRAM, CONTROL PANEL **X041E**

Siemens-Elema Solna, Sweden | SPS-UD | RX B7-230.051.03.03.02 03.98 | MAMMOMAT 3000 64 60 476

Place labels here!

"Technical Manual"